


## REFURBISHMENT WITH REGULARIZATION ELEMENT

CAP.9.5A





- 1. Concrete with bituminous primer
- 2. Existing vapour barrier membrane
- 3. Existing insulation board
- 4. Existing bituminous membrane
- 5. Regularization element OSB wood with mechanical fixings
- 6. "PLURA THERMO AD" membrane
- 7. Corner reinforcing strip with bituminous membrane BPP 4 mm
- 8. "PRATIKO G200 MINERAL 4 mm ON SELVEDGE", with colourless fixative coating "SLATEFIX"
- 9. Reinforced corner with double layer of bituminous membrane "PRATIKO G200 MINERAL 4 mm ON SELVEDGE", with colourless fixative coating "SLATEFIX"
- 10. Metal flashing with mechanical fixings
- 11. Seal with "PRATIKO MASTIC"

## **ALTERNATIVE:**

12. Clip on flashing with mechanical fastening