


TEL. +39 045 6608111 FAX +39 045 6608177 www.pluvitec.c

REFURBISHMENT WITH NEW INSULATION ELEMENT

CAP.9.6





- 1. Concrete with bituminous primer
- 2. Existing vapour barrier membrane
- 3. Existing insulation board
- 4. Existing bituminous membrane
- 5. New insulation board
- 6. Mechanical fixings
- 7. "PLURA THERMO AD" membrane
- 8. Corner reinforcing strip with bituminous membrane BPP 4 mm
- "PRATIKO G200 MINERAL 4 mm ON SELVEDGE", with colourless fixative coating "SLATEFIX"
- 10. Reinforced corner with double layer of bituminous membrane "PRATIKO G200 MINERAL 4 mm ON SELVEDGE", with colourless fixative coating "SLATEFIX"
- 11. Metal flashing with mechanical fixings
- 12. Seal with "PRATIKO MASTIC"

ALTERNATIVE:

Clip on flashing with mechanical fastening